

# MPI Fringe Tracker Anomaly

Greg Neat

Alex Abramovichi

Rob Calvet

2/21/97



# Presentation Outline

I. Fringe Tracker Description


II. Tests Performed

III. Solutions/Repairs


IV. Implications for SIM




## Schematic Diagram of Inherited Optical Path Delay Line Trolley



## MPI TESTBED FRINGE TRACKER BLOCK DIAGRAM




Loop Gains for voice coil (b), pzt (y), and sum (p)





VG to PZT Ratio Transfer Function, Mag and Phase




# Tests Performed


1. Time Capture of OPD and PZT command
2. Voice Coil Plant Transfer Function Measurement
3. Voice Coil-to- Accelerometer Transfer Function Measurement
4. PZT Tests
  - measure transfer function
  - rotate secondary and reactuator shafts
  - remove secondary and reactuator completely
  - replace with dummy Al shaft
  - add mass
5. Add Masses




Plot of pzt command (p) and opd (y) during instability





Plot of pzt command (p) and opd (y) in marginally stable condition



Comparison of Voice Coil Plant TF before and after Malfunction



Comparison of vc plant tf to vc-to-z accel on cats eye tf



# Tests Performed (continued)

## 6. Flexure Checkout

- inspection
- measure 1 Hz mode

## 7. Assess Voice Coil Transfer Function Linearity

## 8. Focus Delay Line

## 9. Switch Voice Coils

## 10. Switch Voice Coil Amps

## 11. Voice Coil Transfer Function at Different Cart Positions


## 12. Change Cart Boundary Conditions

## 13. 100 Hz Drive (low amplitude)


## 14. 100 Hz Drive (high amplitude)



Comparison of vc transfer function for orig, inboard, outboard




## What Happened ?





Comparison of vc plant tfs before and after anomaly



# Implications for SIM

Perform on-orbit?	Tests Performed
yes	1. Time Capture of OPD and PZT command
yes	2. Voice Coil Plant Transfer Function Measurement
?	3. Voice Coil-to- Accelerometer Transfer Function Measurement
	4. PZT Tests
yes	- measure transfer function
no	- rotate secondary and reactuator shafts
no	- remove secondary and reactuator completely
no	- replace with dummy AI shaft
no	- add mass
no	5. Add Masses
	6. Flexure Checkout
no	- inspection
yes	- measure 1 Hz mode
yes	7. Assess Voice Coil Transfer Function Linearity
?	8. Focus Delay Line
no	9. Switch Voice Coils
?	10. Switch Voice Coil Amps
yes	11. Voice Coil Transfer Function at Different Cart Positions
yes	12. Change Cart Boundary Conditions
yes	13. 100 Hz Drive (low amplitude)
?	14. 100 Hz Drive (high amplitude)

# Implications for SIM

Given that the anomaly occurred, what would we do about it?.....

	on ground	on orbit
fix it	- mechanically tune	- switch delay lines (need redundancy)
live with it	- no way	- redesign fringe tracker and pointing loops

# Implications for SIM

How could this condition have been avoided on SIM?

1. System Level Design Issues
  - momentum compensate the voice coils
  - avoid local “mode stacking”
  - actuator isolation
2. Model Fidelity not Sufficient to Predict this Problem
  - try to identify troublesome areas and put fidelity there
3. Add Accelerometers to Sensor Suit for Problem Diagnosis
  - locate in anticipated troublesome areas
4. Suggestions for Software Fault Detection and Recovery
  - capable of reconfiguring to a more complex control configuration
  - accommodate suite of diagnostic tests
5. Include a Redundant Delay Line